

Failure Analysis in Mechanical Engineering: **the Toyota 2AZ-FE**

A literature-based investigation of oil consumption, piston-ring behavior, testing limits, and a more defensible path to prevention.

JOHN COTELO

Original paper: March 2024 | Revised edition: October 2026

The central finding is direct: Toyota documented abnormal oil consumption in affected 2AZ-FE applications and changed the piston assembly to reduce it. Published piston-ring research helps explain a credible transport mechanism, but it does not prove Toyota's internal design decisions or development history. This revision keeps that evidence boundary clear.

What failed, what the evidence supports, and what should change

The Toyota 2AZ-FE is a useful failure-analysis case because the visible symptom - excessive engine-oil consumption - sits at the intersection of component geometry, lubrication, pressure, temperature, load, wear, and maintenance. Toyota service bulletins state that some vehicles equipped with 2AZ-FE or 2AZ-FXE engines may exhibit oil consumption and that the piston assembly was changed to minimize the condition [1, 2]. That statement establishes the field problem and the production response without requiring speculation about what Toyota did or did not test during development.

The most defensible explanation is not that one ring simply wore out at one predictable mileage. Piston rings must seal combustion pressure, control oil on the cylinder wall, and move with very low friction. Published work on ring-groove flow and transient oil transport shows how pressure changes, engine speed, load transitions, and the amount of oil stored around the ring pack can move oil toward the combustion chamber [3, 4]. Wear and carbon accumulation can make the condition worse, but the available evidence points to a system-level interaction instead of one isolated material failure.

The recommended response is equally system-level: combine FMEA with representative engine testing that includes thermal cycling, sustained high speed, sudden load changes, oil aging, drainback behavior, and longer-duration deposit formation. A friction or wear test is valuable, but a standard test by itself cannot recreate every coupled condition inside an operating engine.

WHAT IS ESTABLISHED	WHAT IS INFERRED
Toyota documented oil consumption in affected 2AZ engines and issued inspection and repair procedures. Toyota also stated that the piston assembly was changed to minimize oil consumption.	Published ring-pack research provides a credible mechanism for oil transport under changing pressure, speed, and load. It supports the explanation, but it is not a direct record of Toyota's internal root-cause process.

PAPER MAP

1. Failure analysis context
2. Preventive analysis and physical testing
3. Case description: the 2AZ-FE oil-consumption condition
4. Investigation: piston-ring oil transport
5. Recommendations and conclusion
6. References

Failure analysis in mechanical engineering

Mechanical engineering covers the design, development, manufacturing, operation, and testing of physical systems. Because these systems fail in different ways, failure analysis cannot be reduced to one test. It is a process of defining the failure, collecting evidence, testing explanations, and determining which combination of design, material, manufacturing, use, and maintenance conditions best explains the result.

The purpose is not only to name a broken part. A useful analysis explains why the system reached that state and how the same result can be prevented. That distinction matters in the 2AZ-FE case because replacing an oil-consuming piston assembly addresses the immediate vehicle, while understanding the pressure, oil-control, and testing conditions addresses the design process.

Failure modes relevant to this case

Fatigue is progressive damage caused by repeated loading. Wear is the gradual loss or change of material at contacting surfaces. A design-related failure occurs when geometry, tolerances, operating conditions, or interactions within the system leave too little margin for real use. These modes can overlap. Wear can reduce sealing performance, carbon can restrict oil-return paths, and a ring-pack geometry can become less tolerant of both conditions over time.

For that reason, this paper does not describe the 2AZ-FE condition as a simple fatigue failure. The evidence supports a piston-assembly oil-control problem whose severity can grow with service conditions, deposits, and wear. The failure is better framed as a system-level oil-management problem than as one ring reaching a universal end-of-life mileage.

Preventive and forensic work

Preventive analysis happens before release or before a known condition produces a field failure. Forensic analysis begins after a failure or abnormal condition has occurred. The same physical test can support either purpose. Ultrasonic inspection, for example, can be used during manufacturing, scheduled in-service inspection, or a post-failure investigation. What makes the work preventive or forensic is the question being asked, not whether the instrument damages the part.

Failure Modes and Effects Analysis

Failure Modes and Effects Analysis (FMEA) is a structured risk-analysis method, not a nondestructive inspection technique. A team identifies possible failure modes, evaluates their effects and causes, and prioritizes action using factors such as severity, occurrence, and detection [7]. In this case, a useful FMEA would connect excessive oil consumption to oil-ring control, drainback, ring-groove pressure, deposits, manufacturing variation, maintenance, and operating conditions. It would then connect each risk to a specific control or test.

Thermo-mechanical fatigue and durability testing

Thermo-mechanical testing combines repeated mechanical loading with temperature changes. It is destructive when the specimen is intentionally driven to damage or failure. For an engine, the broader durability plan should include cold starts, heat soak, high-load operation, speed changes, and repeated thermal cycles because ring clearances, oil viscosity, and gas pressure all change with temperature and operating point.

Ultrasonic inspection and impact testing

Ultrasonic pulse-echo inspection uses reflected sound energy to locate internal discontinuities. It is useful for welds and many other components, but it is not the primary method for diagnosing oil transport through a piston-ring pack. Impact testing, meanwhile, measures the energy a specimen absorbs under rapid loading. Both methods are important in mechanical engineering; neither directly reproduces the lubrication and pressure behavior at the center of this case.

Relevant ASTM standards

ASTM G181 provides a method for friction testing piston-ring and cylinder-liner materials under lubricated conditions [5]. ASTM G206 guides the measurement of wear volumes in piston-ring segments tested against flat coupons [6]. These standards help produce repeatable material and wear data. Their limitation is scope: a controlled coupon or segment test cannot reproduce the full ring pack, combustion pressure, oil drainback, deposits, temperature gradients, and transient engine operation at the same time.

The Toyota 2AZ-FE oil-consumption condition

Toyota Technical Service Bulletin T-SB-0094-11 states that some 2006-2011 model-year vehicles equipped with the 2AZ-FE engine may exhibit engine oil consumption. The bulletin directs technicians through a repair procedure and states that the piston assembly was changed to minimize oil consumption [1]. A related inspection bulletin covers the test used to confirm the condition in affected 2AZ-FE and 2AZ-FXE applications [2]. These documents establish both the field symptom and Toyota's piston-assembly response. They do not call the condition a safety recall, and this paper does not treat it as one.

What the piston rings must do

The piston rings sit between the piston and cylinder liner. Together, the ring pack must seal combustion pressure, transfer heat, maintain a controlled lubricant film, and scrape excess oil away from the combustion chamber. Those jobs work against each other. Higher ring tension can improve oil control, but it also raises friction. Lower tension can reduce mechanical loss, but it can reduce the margin available when pressure, oil supply, deposits, geometry, or wear move away from the intended condition.

When oil reaches the combustion chamber, it can burn with the air-fuel mixture. The owner may notice a falling oil level, smoke in some conditions, spark-plug fouling, reduced catalyst life, deposits, or a misfire code. The severity and mileage at which symptoms appear can vary, so the analysis should not imply that every affected engine fails at one specific odometer reading.

How pressure and oil move through the ring pack




Figure 1. Flexible piston-ring model and ring-groove control volumes used to study gas blow-by and pressure behind the ring. Adapted from Turnbull et al. [8]. The diagram is useful because it shows why oil control depends on the full ring-groove-liner system, not only the ring material.

The left side visualizes gas flow and pressure around a flexible ring. The right side separates the groove into control volumes. Read together, they show how pressure can act on different ring surfaces while lubricant occupies the small spaces between the piston, ring, and cylinder liner.

This is the core system view used in the investigation: ring tension matters, but so do the pressure field, groove geometry, lubricant film, oil-return path, and the operating transition that changes them.

A credible oil-transport mechanism

Low-tension rings are used to reduce frictional losses. That choice is not automatically a defect; it is an engineering tradeoff. The important question is whether the complete piston and ring system controls oil across the expected range of load, speed, temperature, wear, deposits, and manufacturing variation.

Kawamoto et al. modeled gas-liquid two-phase flow inside a piston-ring groove and investigated how gas flow and pressure influence oil behavior [3]. Li and Tian used an optical engine to study oil transport during a transition from low load to high load [4]. Their work shows why a sudden operating change matters: pressure and oil stored around the ring pack do not remain static as the engine moves to a new load. Oil can be displaced toward the combustion chamber during the transient.

What these results mean for the 2AZ-FE is narrower than the original paper claimed. They provide a technically plausible mechanism that is consistent with a piston-assembly oil-control condition. They do not prove that Toyota omitted a particular test, and they do not isolate one feature of the 2AZ-FE as the only cause. The Toyota bulletins establish the condition and the production change; the research explains how comparable ring-pack physics can move oil.

Why standard tests were not enough by themselves

ASTM G181 and G206 address friction and wear measurements, which are necessary pieces of the problem. However, neither standard is intended to duplicate an entire firing engine. A design could perform acceptably in material-level friction and wear testing while still showing unacceptable oil control when transient pressure, drainback, oil aging, and deposits interact. The gap is not a failure of the standards; it is a reminder that component standards must be paired with system-level validation.

Root-cause statement

The available evidence supports a piston-assembly oil-control problem in affected 2AZ-FE applications. Toyota's revised piston assembly is direct evidence that the original configuration did not provide sufficient oil-control performance in every field condition. Published research supports a mechanism involving ring-groove pressure and oil transport. Wear and deposits can increase the severity, but the evidence does not support reducing the condition to ordinary fatigue alone.

Test the interaction, not only the component

Toyota's service response used an oil-consumption inspection procedure followed by a piston-assembly repair procedure for vehicles that met the bulletin's criteria [1, 2]. For future development, the strongest preventive action is not simply to avoid low-tension rings. They offer a real efficiency benefit. The better response is to validate the full oil-control system under conditions that make the tradeoff difficult.

Recommended validation plan

- Use FMEA to connect excessive oil consumption to ring tension, groove geometry, drainback, oil supply, deposits, blow-by pressure, thermal expansion, tolerance variation, and maintenance.
- Run abrupt low-to-high-load transitions and sustained high-speed operation while measuring oil consumption, crankcase pressure, blow-by, and emissions.
- Include repeated cold starts, heat soak, thermal cycling, and aged oil so viscosity and deposit formation are represented.
- Test across manufacturing tolerances instead of validating only nominal parts. The worst-case stackup can matter more than the average configuration.
- Correlate material-level friction and wear results with a firing-engine durability test. Standards should support the program, not define its complete boundary.
- Inspect returned field hardware and feed deposit, wear, and oil-return observations back into the design FMEA and validation matrix.

Oil viscosity

Changing oil viscosity should not be presented as a general fix without a validated engine-specific recommendation. Viscosity affects pumping, film thickness, flow through small passages, startup lubrication, and drag. Any change would need testing across the complete operating range and would need to remain consistent with the manufacturer's service requirements.

Conclusion

The 2AZ-FE case shows why failure analysis is more than identifying a worn part. The field condition was excessive oil consumption, Toyota's repair centered on the piston assembly, and published ring-pack research supplies a reasonable physical explanation for how operating conditions can move oil toward the combustion chamber. The most useful engineering lesson is to protect the friction benefit of low-tension rings with validation that captures the coupled pressure, temperature, oil, deposit, geometry, and wear conditions of a real engine.

A clear evidence boundary makes the conclusion stronger: the Toyota bulletins establish the condition and corrective direction; the research explains a plausible mechanism; and the recommendations translate both into a more complete test plan.

References

- [1] Toyota Motor Sales, USA, Inc., 2AZ-FE Engine Oil Consumption, Technical Service Bulletin T-SB-0094-11 Rev2, Aug. 11, 2011, revised 2015. Available: static.nhtsa.gov/odi/tsbs/2015/MC-10111356-9999.pdf.
- [2] Toyota Motor Sales, USA, Inc., 2AZ Engine Oil Consumption Inspection Procedure, Technical Service Bulletin T-SB-0158-14 Rev2, Dec. 12, 2014, revised 2015. Available: static.nhtsa.gov/odi/tsbs/2015/MC-10111394-9999.pdf.
- [3] Y. Kawamoto, S. Takahashi, M. Ochiai, A. Azetsu, and K. Yamamoto, "Prediction of oil behavior in piston ring groove based on gas-liquid two-phase flow analysis," *Journal of Advanced Mechanical Design, Systems, and Manufacturing*, vol. 14, no. 6, 2020. doi: 10.1299/jamdsm.2020jamdsm0081.
- [4] M. Li and T. Tian, "Experimental Investigation of Oil Transport during Low Load to High Load Transient in Internal Combustion Engines," *Lubricants*, vol. 11, no. 2, p. 76, 2023. doi: 10.3390/lubricants11020076.
- [5] ASTM International, ASTM G181-21: Standard Test Method for Conducting Friction Tests of Piston Ring and Cylinder Liner Materials Under Lubricated Conditions, 2021.
- [6] ASTM International, ASTM G206-17: Standard Guide for Measuring the Wear Volumes of Piston Ring Segments Run Against Flat Coupons in Reciprocating Wear Tests, 2017.
- [7] H.-C. Liu, L.-E. Wang, Z. Li, and Y.-P. Hu, "Improving Risk Evaluation in FMEA With Cloud Model and Hierarchical TOPSIS Method," *IEEE Transactions on Fuzzy Systems*, vol. 27, no. 1, pp. 84-95, 2019. doi: 10.1109/TFUZZ.2018.2861719.
- [8] R. Turnbull, N. Dolatabadi, R. Rahmani, and H. Rahnejat, "An assessment of gas power leakage and frictional losses from the top compression ring of internal combustion engines," *Tribology International*, vol. 142, 2020. Figure adapted from the flexible piston-ring and gas blow-by model reproduced in the original paper.

Revision note: This edition corrects the classification of FMEA, separates preventive/forensic purpose from destructive/nondestructive test type, removes unsupported mileage and development-process claims, and anchors the 2AZ-FE case in Toyota's published service information.